



POWERMAX™ -USB/RS USER MANUAL ADDENDUM

This addendum modifies the *PowerMax-USB/RS User Manual* (part number 1169780). The PowerMax-RS sensors communicate over an RS-232 port using the RS-232 settings shown below.

RS-232 Port Settings

Baud rate: 9600
Data bits: 8
Parity: None
Stop bits: 1
Flow control: None

Questions?

Call: (USA) 1.800.343.4912
(Europe) +49-6071-968-0
(International) 503.454.5700

or visit our website: www.Coherent.com

PowerMax™-USB/RS User Manual Addendum
© Coherent, Inc., 3/2010, (RoHS). Printed in the U.S.A.
Part No. V007602